

REFRIGERATED EQUIPMENT MANUFACTURERS		Project Name: _____	AIA #
		Location: _____	SIS #
Item # _____ Qty: _____			
Model #: _____			
Model: 681HC	MILK CASE COOLER 8 Case Hydrocarbon Refrigeration		

STANDARD FEATURES

- NSF and ETL approved.
- R290 hydrocarbon refrigerant is used to comply with all environmental standards. R290 has zero ozone depletion potential (ODP) and three global warming potential (GWP).
- Powder-coat or stainless steel exterior finish.
- All copper tubing
- 2" Non-CFC foamed in place polyurethane insulated cabinet and lids.
- Removable plastic, easily cleanable racks.
- Vinyl gasket is removeable without tools.
- Slam latches on lower lid.
- 8 foot power cord, 115V 60HZ.
- Stainless steel hinges and latches.
- Casters.
- Energy efficient - no interior fan.
- Low maintenance.
- Self contained, ready to plug in.
- 2" dial thermometer
- Bottom drain.
- Stainless steel top and lids; heavy gauge, alumimun interior.
- One year parts and labor warranty.
- Five year compressor motor warranty.



Dimensions			Volume/ Cu. Ft.	Amps	Voltage	Unit HP Required	Bottom Racks	Doors/ Lids
W	D	H						
33"	31"	40 ½"	11.2	3.7	115	1/5	2	2



Model:	MILK CASE COOLER 8 Case Hydrocarbon Refrigeration
681HC	

MODEL		681
INTERNAL DIMENSIONS		
Width	28 ¾"	
Depth	27"	
Height	25"	
CAPACITY		
13x13 Case 16 qt. capacity	8	
13X16 Case 20 qt. capacity	4	
13X19 Case 24 qt. capacity	4	
SHIPPING DETAILS		
Weight	220 lbs	
Height - Crated	60"	
Width - Crated	36"	
Depth - Crated	36"	
ELECTRICAL REQUIREMENTS		

connection to a 115/60/1 phase, 15 amp dedicated outlet.



WARRANTY

start-up, normal adjustments, or maintenance.
OEM parts needed for warranty must be obtained from Powers Equipment.

Five Year Compressor Warranty

Powers warrants to the original purchaser for a period of five years from the date of installation, that we will replace the compressor on the unit if found, in the reasonable opinion of the factory, to be defective in material or workmanship. Relays, overloads, capacitors, and any other electrical components are not included in the five-year warranty.

Model Views

